

00684.003580

PATENT APPLICATION

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:)	
	:	Examiner: Leonard S. Liang
NORIKO SATO)	
	:	Group Art Unit: 2853
Application No.: 10/764,547)	
	:	Confirmation No.: 9608
Filed: January 27, 2004)	
	:	
For: RECORDING APPARATUS)	January 23, 2009
	:	
Patent No.: US 7,314,265 B2)	
	:	
Issued: January 1, 2008)	

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULE 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (PTO-1050) is enclosed.

The \$100.00 fee for the Certificate of Correction is being paid electronically. The Commissioner is authorized to charge any underpayment or credit any overpayment to Deposit Account No. 06-1205.

Patentee's undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

/Edmund J. Haughey/

Edmund J. Haughey
Attorney for Patentee
Registration No. 44,749

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200
EJH:ayr

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 7,314,265 B2

DATED : January 1, 2008

INVENTOR(S) : SATO

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 22, "toward" should read --toward a--.

Line 34, "out" should read --our--.

Line 46, "which" should read --which a--.

COLUMN 2:

Line 25, "to" should read --to the--, and "of" should read --of the--.

Line 58, "in" should be deleted.

COLUMN 5:

Line 9, "an" should read --and--.

COLUMN 6:

Line 24, "carriage 40" should read --carriage 401--.

COLUMN 7:

Line 33, "above" should read --above- --.

Line 43, "carriage 402." should read --carriage 401.--.

COLUMN 8:

Line 16, "has only" should read --only has--, and "be" should be deleted.

Line 18, "cleaning" should read --clean--.

Line 47, "heat" should read --head--.

Line 57, "latch" should be deleted.

Line 59, "above described" should read --above-described--.

Line 62, "above described" should read --above-described--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 7,314,265 B2

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 7,314,265 B2

DATED : January 1, 2008

INVENTOR(S) : SATO

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 9:

Line 1, "scale 402," should read --scale 408,--.

Line 45, "above described" should read --above-described--.

Line 49, "above described" should read --above-described--.

COLUMN 10:

Line 21, "in" should read --in the--.

Line 25, "above described" should read --above-described--.

Line 46, "above described" should read --above-described--.

Line 48, "above described" should read --above-described--.

COLUMN 11:

Line 11, "subjected" should read --subjected to--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 7,314,265 B2

No. of add'l. copies
@ 30¢ per page

